Solid system

How to install:

Probe installation

Probe connection:

Inlet istallation

Power supply:

Water connection:

Trouble shooting:



JYSK KEMI SERVICE A/S

Ready
to go!!



JYSK KEMI SERVICE A/S

Looks good!!



JYSK KEMI SERVICE A/S

Ready to go installation.







JYSK KEMI SERVICE A/S



Drill

Where to install probe and inlet








View of probe from under washtank







Resistor on conductivity probe





Inlet from dosing equipment:











Electric connections:








How to connect vater to dosing equipment:



How to ajust Circuit board:

A. Alarm time:
B. Detergent dosing:
C. Rinse aid leve device connection:



Jumper off:
Viking Probe

Jumper on:
SEKO probe

Info for user how to replace solid container



You have done a good job



Trouble shooting:

1. Spray nozzle clogged:
2. Over flowing, Inserting screen
3. There’s drilled hole in new dosing devises
4. Water running constantly / dirt in Watervalve
5. Cleaning watervalve
6. Foam around probe cause overdose





Demo video



How to clean water valve:

Screw pinn out and open to inside. Remove dirt on rubber seal. Rinse with water and put back together again.

